

FIG. 1




FIG. 2






FIG. 3





# Drain Side Program Rate Distribution After UV Erase




FIG. 6

FOOTNOTES 4004460

Source Side Program Rate Distribution After UV Erase




FIG 7




FIG 8



100460 2002260




FIG. 9